

142207, . , RU.0001.11 26 » 21.03.2007 . , 17; .(4967) 76 18 89

CN.M 26. 00225

18

2010

FORSAGE, LEIKE

LK50GY-2

-

-

L1

8711 10

VIN

LD6LCB02?...

« », 426054, . , .9- -
, .31,

Zhejiang Leike Machine Industry Co., Ltd No 191,
Chang Hong East Road, Song Yang Town, Zhej iang,
323400, P.R. China

2,

/

2×1 /

	2
-	1930
-	690
-	1025
	1340
-	108
	258
-	86
-	172
()	Zhejiang Leike Machine Industry Co., Ltd, LK139QMB,
-	1,
-	49,5
-	10,5
(1/)	1,68 (8200)
(1/)	2,58 (3800)

POCC CN.MT26.E00225

, 1 , -

(,) Dashun, PD 19J
(,) HB, e4 KL-03, -

.D.I- ,
(,) SM0604
(,) LFP0712
(,) Zhuzhou Torch Spark Plug Co., A7RTC

(,) e4 XS-04 c -

(,) , - -

- 1,51
- 2,86

- (,) 11,05

- - -

- - -

(,)

- (,) ,
Zheji-
ang Songyang LeiTian Brake Co., Ltd
- China Songyang
LeiTian Brake Co., Ltd ,

- (,)

0039423

SERTAUTO.RU

N. 26. 00225

-	,	130/60-13	3.00-10	130/70-12
-	,	-		-
-	,	53		56
-		J		J

SERTAUTO.RU

FORSAGE, LEIKE LK50GY-2

3 1 . 2

« »

..

..

18 2009 .

SERTAUTO.RU

P CN. 26. 00225

1 « »

” ‘ ” ” ”

1	2	3
(97/24/8, 2002/24 10-02) -	RDW Vehicle Technology Division THE NETHERLANDS	4*2002/24*1681*00
(97/24 /5, 2002/24 47-00)		
(97/24/2, 2002/24 50-00)	- “ -	- “ -
(93/29, 2002/24 60-00)	- “ -	- “ -
(93/33, 2002/24 62-00)	- “ -	- “ -
(97/24/9, 2002/24 63-01)	- “ -	- “ -

1	2	3
(93/92, 2002/24 74-01) -	RDW Vehicle Technology Division THE NETHERLANDS	4*2002/24*1681*00
(97/24/1, 2002/24 75-00)		
(93/14, 2002/24 78-02)	- “ -	- “ -
(97/24/4, 2002/24 81-00)	- “ -	- “ -
(93/34, 2002/24 51980, 37.001.269 .5)	- “ -	- “ -

« » ,
 _____ . . ,
 _____ . . ,

2 « »

1.

50460-92

2.

3.

(VIN):

3.1

3.2

4.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
L	D	6	L	C	B	0	2	?	?	?	?	?	?	?	?	?

. 1÷3: LD6 – (WMI):
Zhejiang Leike Machine Industry Co., Ltd No 191, Chang Hong East
Road, Song Yang Town, Zhejiang, 323400, P.R. China

. 4÷8: LCB02– (LK50GY-2)

. 9: ? – : 0 9

. 10: ? – : 9 – 2009 .; – 2010 .

. 11÷17 ??? -

